

Inspection Photos

September 28, 2022

Operator: Argali Exploration Company - #3975

Location ID: 313288

Location Name: Simpson-68N90W /24NESW

Inspection Document #: 702800778

Moffat County, CO

NESW Section 24 T8N R90W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Simpson-68N90W /24NESW
Location ID: 313288



Photo 1. Photo taken from the east shows an overview of the Location. Note where tank has been removed and battery dismantled.

Inspection Photos
Location Name: Simpson-68N90W /24NESW
Location ID: 313288



Photo 2. Photo shows a meter run with no equipment and a knocked over tank. Equipment is now debris.



Photo 3. Refer to Photo 2 comment.



Inspection Photos
Location Name: Simpson-68N90W /24NESW
Location ID: 313288



Photo 4. Photo taken from the east shows the tank battery site, where a tank has been removed.



Photo 5. Photo taken from the southeast shows the tank battery site, where a tank has been removed.



Inspection Photos
Location Name: Simpson-68N90W /24NESW
Location ID: 313288



Photo 6. Photo shows the wellhead. Photo also shows an example of debris found on Location.



Photo 7. Photo shows an anchor marker in disrepair.

Inspection Photos
Location Name: Simpson-68N90W /24NESW
Location ID: 313288



Photo 8. Photos show areas at the at the west of the Location where jointed goatgrass is common.

