

# Inspection Photos

September 28, 2022

Operator: Lyster Oil Company Inc - #51922

Location ID: 399271

Location Name: Grassy Creek State-66N86W /31NWNW

Inspection Document #: 702800759

Routt County, CO

NWNW Section 31 T6N R86W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: Grassy Creek State-66N86W /31NWNW

Location ID: 399271



**Photo 1.** Photo taken from the south, at the top of the cut slope shows an overview of the unreclaimed Location.



**Photo 2.** Photo taken from the center of the Location shows an overview of the flat, gravelled pad and eroding cut slope. The Location has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800759



## Inspection Photos

Location Name: Grassy Creek State-66N86W /31NWNW

Location ID: 399271



**Photo 3.** Photo taken from the south shows the eroding cut slope. Note undercutting and exposed roots in reference area.



**Photo 4.** Refer to Photo 3 comment.



## Inspection Photos

Location Name: Grassy Creek State-66N86W /31NWNW

Location ID: 399271



**Photo 5.** Photo taken from the north of the Location at the base of the fill slope. The red arrow indicates where gully erosion is occurring.



**Photo 6.** Photo taken from the north of the Location at the top of the fill slope shows gully erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800759



## Inspection Photos

Location Name: Grassy Creek State-66N86W /31NWNW

Location ID: 399271



**Photo 7.** Photo shows gully erosion in the fill slope.



**Photo 8.** Photo shows gully erosion in the fill slope.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800759



## Inspection Photos

Location Name: Grassy Creek State-66N86W /31NWNW

Location ID: 399271



**Photo 9.** Photo taken from the center of the Location shows the pad surface is flat, graveled and compacted. Note also mullein (List C Noxious).



**Photo 10.** Photo taken from the center of the Location shows the pad surface is flat, graveled and compacted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800759



## Inspection Photos

Location Name: Grassy Creek State-66N86W /31NWNW

Location ID: 399271



**Photo 11.** Photo taken from the northwest shows the center pit. Three former pits are unreclaimed. Note eroding cut slope, bare soil, trash and pipe (red arrow).



**Photo 12.** Photo shows the pipe at the center pit.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800759



## Inspection Photos

Location Name: Grassy Creek State-66N86W /31NWNW

Location ID: 399271



**Photo 13.** Photo taken from the north of the Location shows the southernmost pit. Three former pits are unreclaimed. Note Canada thistle (List B Noxious).



**Photo 14.** Photo taken from the north of the Location shows the easternmost pit. Three former pits are unreclaimed. Note bare soil.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800759



Inspection Photos  
Location Name: Grassy Creek State-66N86W /31NWNW  
Location ID: 399271



**Photo 15.** Photos show the reference area vegetation to the south of the Location.

