

Inspection Photos
Location Name: Bondad 33-9
Location ID: 326440



IMG 01
Well sign



IMG 02
Location overview



IMG 03
Erosion from upgradient



IMG 04
Sediment from upgradient



IMG 05

Erosion channel along access road



IMG 06

Erosion channel along access road



IMG 07

Erosion channel along access road

IMG 08