

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W /8SESW

Location ID: 335054



Photo #7940 From entrance to location.



Photo #7941 location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W /8SESW

Location ID: 335054



Photo #7942 Location lacks stabilization.



Photo #7943 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CSF-67S91W /8SESW

Location ID: 335054



Photo #7944 Insufficient tracking BMP at entrance to location.