

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE-66S92W /34SWSE

Location ID: 324246



Photo #7958 From entrance to location.



Photo #7959 From entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE-66S92W /34SWSE

Location ID: 324246



Photo #7960 From entrance to location.



Photo #7961 Unused equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE-66S92W /34SWSE

Location ID: 324246



Photo #7963 Unused equipment.