

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE-66S92W /34SESE

Location ID: 324247



Photo #7977 From entrance to location.



Photo #7978 From entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE-66S92W /34SESE

Location ID: 324247



Photo #7981 Unused equipment.



Photo #7982 unused equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE-66S92W /34SESE

Location ID: 324247



Photo #7983 Unused equipment.



Photo #7984 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE-66S92W /34SESE

Location ID: 324247



Photo #7985 Location lacks stabilization.



Photo #7986 Insufficient tracking BMP at entrance to location.