

Inspection Photos

API: 055-06209

Operator: CAPTUREPOINT LLC

Inspection Date: 10/6/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06209 | Date: 10/6/2022

Inspection Photos



Photo 1. Facing south along the access road. There are noxious weeds along the road that need to be controlled. Red arrow → Scotch thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06209 | Date: 10/6/2022

Inspection Photos



Photo 2. Facing southeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06209 | Date: 10/6/2022