

Inspection Photos

API: 055-06285

Operator: CAPTUREPOINT LLC

Inspection Date: 10/6/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 10/6/2022

Inspection Photos



Photo 1. Facing northwest toward the location. There are still numerous noxious weeds that need to be controlled. Red arrow → Scotch thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 10/6/2022

Inspection Photos



Photo 2. Facing northwest toward the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 10/6/2022

Inspection Photos



Photo 3. Facing north west at the location. There is numerous noxious weeds at the location that need to be controlled. The weeds have produced seed heads and dispersed seed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 10/6/2022

Inspection Photos



Photo 4. There are numerous noxious weeds at the location. The Scotch thistle Rosettes will grow back next year. Ongoing weed control is required.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06285 | Date: 10/6/2022