

Inspection Photos
Well Name: North Platte P-T-28HNC
API #05-123-46914



Photo #1 Well

Photo #2 Trash

Inspection Photos
Well Name: North Platte P-T-28HNC
API #05-123-46914



Photo #3 Mechanical Conditions

Photo #4 Stained Soil