

Inspection Photos
Location Name: North Platte 41-28 Pad
Location ID: 332135



Photo #1 Unused Equipment

Photo #2 Unused Equipment

Inspection Photos
Location Name: North Platte 41-28 Pad
Location ID: 332135



Photo #3 Unused Equipment

Photo #4 Unused Equipment

Inspection Photos
Location Name: North Platte 41-28 Pad
Location ID: 332135



Photo #5 Unused Equipment



Photo #6 Unused Equipment

Inspection Photos
Location Name: North Platte 41-28 Pad
Location ID: 332135



Photo #7 Stained soil

Photo #8 Stained soil

Inspection Photos
Location Name: North Platte 41-28 Pad
Location ID: 332135



Photo #9 Mechanical Conditions

Photo #10 Open Hole

Inspection Photos
Location Name: North Platte 41-28 Pad
Location ID: 332135



Photo #11 Stained Soil

Photo #12 Stained Soil