

Inspection Photos
Location Name: Chandler Creek # 22-32
Location ID: 422357



Photo 1 Well head. No well head sign



Photo 2 stained soil

Inspection Photos
Location Name: Chandler Creek # 22-32
Location ID: 422357



Photo 3 stained soil around PU



Photo 4 Weeds around well head.

Inspection Photos
Location Name: Chandler Creek # 22-32
Location ID: 422357



Colorado Oil and Gas Conservation Commission
38.35418, -105.13751, 1636.0m
Oct 11, 2022 1:52:21 PM

Photo 5 guyline anchor not marked.



Colorado Oil and Gas Conservation Commission
38.35297, -105.13687, 1625.0m
Oct 11, 2022 1:55:31 PM

Photo 6 TNK BTR

Inspection Photos
Location Name: Chandler Creek # 22-32
Location ID: 422357



Photo 7 stained soil crude oil load line



Photo 8 weeds in crude oil tank containment.