



Marble 34-33





Complied with Rule 1002.f.(2)B, Complied with general provisions of the oil and gas act for wildlife protection and SB-181.





Installed appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1),





Removed all trash and debris from location per Rule 606. Maintained vegetation around location per Rule 606.