

Final Reclamation Inspection

August 1st, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 331416

Inspection Document #: 701900483

NENE Section 21 T4N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Fickel 41-21
Location ID: 331416



Photo 1. 2021 aerial imagery of the access road, well pad and associated tank battery.

Inspection Photos
Location Name: Fickel 41-21
Location ID: 331416




Photo 2. Overview photo of the well pad, access road, reference area and tank battery taken with a drone. Note: well pad and access road appear consistent with adjacent reference area. Tank battery is on the 2022 schedule maintenance list and will receive a no status until the site can be re-inspected during the next growing season in 2023.