

Final Reclamation Inspection

August 4th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 322556

Inspection Document #: 701900544

NWSW Section 27 T6N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Koehler Frank 13-27
Location ID: 322556



Photo 1. 2021 aerial imagery of the well pad, tank battery and access road.

Inspection Photos
Location Name: Koehler Frank 13-27
Location ID: 322556




Photo 2. Overview photo of the well pad, access road and reference area taken from the southern edge facing north using a drone. Note: well pad and access road appear consistent with adjacent crop reference area.

Inspection Photos
Location Name: Koehler Frank 13-27
Location ID: 322556



Photo 3. Overview photo of the tank battery and reference area. Note: tank battery access remains with a culvert indicated by white arrow (see photo 4). Remaining tank battery disturbance appears consistent with adjacent crop reference area.

Inspection Photos
Location Name: Koehler Frank 13-27
Location ID: 322556



Photo 3. Ground photo of the tank battery access point and culvert that remain on site.