

Final Reclamation Inspection

August 5th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 327516

Inspection Document #: 701900559

SESE Section 13 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hoshiko 4
Location ID: 327516



Photo 1. 2021 aerial imagery of the well pad, access road and tank battery.

Inspection Photos
Location Name: Hoshiko 4
Location ID: 327516




Photo 2. Overview photo of the well pad, access road and reference area taken from the southern edge facing north using a drone. Note: well pad and access road appear consistent with adjacent crop reference area.

Inspection Photos
Location Name: Hoshiko 4
Location ID: 327516



Photo 3. Overview photo of the tank battery taken at ground level from the western edge facing east.

Inspection Photos
Location Name: Hoshiko 4
Location ID: 327516



Photo 4. Monitoring well observed on site, however no open remediation at the location..