

Final Reclamation and Stormwater Inspection

Date: 10/07/2022

Operator: PINTAIL PETROLEUM LTD - 70430

Location ID: 411332

Inspection Document #: 696105487

Yuma County, CO

SWNE Section 8 T2S R47W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SALZMAN #1
Location ID: 411332



Photo 1. Taken from location, facing south. It appears operator has performed final reclamation activities with no visual evidence of oil and gas equipment observed. Annual weedy vegetation (e.g. kochia) was observed throughout the location, outlined in red.

Inspection Photos
Location Name: SALZMAN #1
Location ID: 411332



Photo 2. Facing west, see comments in Photo 1.

Inspection Photos
Location Name: SALZMAN #1
Location ID: 411332



Photo 3. Facing north, see comments in Photo 1.

Inspection Photos
Location Name: SALZMAN #1
Location ID: 411332



Photo 4. Facing east, see comments in Photo 1.