

# Final Reclamation and Stormwater Inspection

Date: 10/07/2022

Operator: MCELVAIN ENERGY INC - 55575

Location ID: 411786

Inspection Document #: 696105489

Yuma County, CO

Lot 1 Section 18 T2S R46W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: MAROON #18-4  
Location ID: 411786




**Photo 1.** Taken near access road entrance, facing south east. Photo shows that access road appears to be contoured and regraded; no evidence of road base/gravel.

Inspection Photos  
Location Name: MAROON #18-4  
Location ID: 411786



**Photo 2.** Taken near location, facing east. Photo shows annual weedy vegetation (e.g. kochia, russian thistle) throughout the location, outlined in red.

Inspection Photos  
Location Name: MAROON #18-4  
Location ID: 411786



**Photo 3.** Taken at location, facing northwest. See comments in Photo 2.

Inspection Photos  
Location Name: MAROON #18-4  
Location ID: 411786



**Photo 4.** Taken from location, facing southwest. See comments in photo 2.