

Inspection Photos

Location Name: CAERUS PICEANCE LLC LAZIER-66S93W /23SESE

Location ID: 335320



Photo #8013 From entrance to location.



Photo #8014 From entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC LAZIER-66S93W /23SESE

Location ID: 335320



Photo #8015 From entrance to location.



Photo #8017 Chemical tank missing required information.

Inspection Photos

Location Name: CAERUS PICEANCE LLC LAZIER-66S93W /23SESE

Location ID: 335320



Photo #8018 Unmarked deadman.



Photo #8019 Heating insulation open ended and not capped.