

Inspection Photos
Location Name: Booth USX EE25-11D Pad
Location ID: 425393



Photo 1: TA Wellhead, NO SIGNAGE



Photo 2: Unused/disconnected equipment

Inspection Photos
Location Name: Booth USX EE25-11D Pad
Location ID: 425393



Photo 3: Unused equipment



Photo 4: Tank Battery