

Inspection Photos  
Location Name: Booth USX EE 23-16  
Location ID: 309909



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos  
Location Name: Booth USX EE 23-16  
Location ID: 309909



Photo 3: Tank Battery Sign



Photo 4: Tank Battery

**Inspection Photos**  
**Location Name: Booth USX EE 23-16**  
**Location ID: 309909**



**Photo 5: Debris**



**Photo 6: Debris**