

Inspection Photos
Location Name: State 36-24-9-61 PAD
Location ID: 419686



Photo 1 – Tank Battery



Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: State 36-24-9-61 PAD
Location ID: 419686



Photo 3 – Heater Treater and ECDs



Photo 4 – Wellhead

Inspection Photos
Location Name: State 36-24-9-61 PAD
Location ID: 419686



Photo 5 – Weeds in the Interim Reclamation Area



Photo 6 – Weeds in the Interim Reclamation Area

Inspection Photos
Location Name: State 36-24-9-61 PAD
Location ID: 419686



Photo 7 – Weeds in the Interim Reclamation Area



Photo 8 – Weeds in the Interim Reclamation Area

Inspection Photos
Location Name: State 36-24-9-61 PAD
Location ID: 419686



Photo 9 – Weeds in Interim Reclamation Area



Photo 10 – Weeds in Interim Reclamation Area