

Inspection Photos
Location Name: Flaschenriem Pad 3-4N-68W
Location ID: 462850



Production facility



Battery sign

Inspection Photos
Location Name: Flaschenriem Pad 3-4N-68W
Location ID: 462850



Master valve leak and stained soil



Master valve leak and stained soil

Inspection Photos
Location Name: Flaschenriem Pad 3-4N-68W
Location ID: 462850



Master valve leak and stained soil



Wellheads