

Inspection Photos

October 10, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 417608

Location Name: GGU Daley /14A-19-691

Inspection Document #: 702800792

Garfield County, CO

SESW Section 19 T6S R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GGU Daley /14A-19-691
Location ID: 417608



Photo 1. Photo taken from the north shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800792

Inspection Photos
Location Name: GGU Daley /14A-19-691
Location ID: 417608



Photo 2. Photo taken from the west shows interim areas and slopes colonized and stabilized by perennial grasses.



Photo 3. Photo taken from the east shows interim areas and slopes colonized and stabilized by perennial grasses.

Inspection Photos
Location Name: GGU Daley /14A-19-691
Location ID: 417608



Photo 4. Photo taken from the northeast shows Russian olive, a CO List B Noxious Weed.



Inspection Photos
Location Name: GGU Daley /14A-19-691
Location ID: 417608



Photo 5. Photo taken from the northeast shows where an enclosed combustor has been removed from the location.



Photo 6. Photo shows production areas at the east of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800792

Inspection Photos
Location Name: GGU Daley /14A-19-691
Location ID: 417608



Photo 7. Photo shows production areas at the north of the location.



Photo 8. Photo shows an overview of production areas from the south of the location.