

Final Reclamation Inspection

October 7, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 328079

Inspection Document #: 697504268

Weld County, CO

NWSW Section 34 T4N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SANDAU #34-12F
Location ID: 328079



Photo 1. COGCC GISOnline aerial imagery illustrating the wells, flowline and tank battery.



Inspection Photos
Location Name: SANDAU #34-12F
Location ID: 328079



Photo 2. Photo taken from the tank battery, facing East. Photo illustrates equipment has not been removed per the Rule 1004.a timing requirements.



Photo 3. Photo taken from the tank battery, facing Northeast. See comments under Photo 2.

