


**Inspection Photos**  
**Location Name: Martinez 1A**  
**Location ID: 320915**



**IMG 01**  
**Well sign**



**IMG 02**  
**Location overview**






**IMG 03**  
**Wellhead**



**IMG 04**  
**Tank sign**





**IMG 05**  
**Tank sign**



**IMG 06**  
**Oily sucker rods**





**IMG 07**

**Oil has impacted surface material**

**IMG 08**