



00241617

WELL SITE INSPECTION

OPERATOR Penalta Corp.

PERMIT NO. _____

WELL NAME Mathewson 32-12

DATE _____

RIG _____

COUNTY Logan

SURFACE CSG SIZE _____ DEPTH _____

LEGAL SWNE S 12 T 9N R 55

DATE _____

CEMENT VOLUME _____ RETURNS _____ WOC _____

PROBABLE FOX HILLS DEPTH & THICKNESS _____

MUD PITS _____

DISPOSAL _____

PROD STRING SIZE _____ DEPTH _____ CMT VOL _____ DATE _____

STAGED _____ CBL CHECKED _____

SQUEEZE _____ FRAC JOB _____

BATTERY _____ SIGN _____

PRESSURE CHECK _____ DATE _____

SITE INSPECTION AFTER DRILLING _____

5/27/87 Pit has 6" freeboard at overflow area.Spill area ~100' X 300'; field plowed around spill areaspill, ~ 4 bbl oil in field, pumpjack presently not
operating. Spill complaint called in, name not given.5/28/87 Called Roland Hart - 307-265-4812 Waiting on ground to dry before dirt work started.

DIRECTIONS _____

ACTION _____

ENGINEER SP