

Inspection Photos

API: 061-06041

Operator: WESTERN OPERATING COMPANY

Inspection Date: 10/12/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06041 - Date: 10/12/2022

Inspection Photos



Photo 1. Facing west at the beginning of the access road. This area needs to be leveled out and reclaimed. The fence needs to be put back to original boundary shown at red line.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 10/12/2022