

Inspection Photos

API: 061-06178

Operator: P O & G OPERATING LLC

Inspection Date: 10/12/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06178 - Date: 10/12/2022

Inspection Photos



Photo 1. Facing south along the access road. The road is not maintained and vehicle are driving around the rutted area causing widening of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06178 - Date: 10/12/2022

Inspection Photos



Photo 2. Facing southeast at the location. There is a pile of soil material stored on location that needs to be removed..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06178 - Date: 10/12/2022

Inspection Photos



Photo 3. Facing toward the tank battery



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06178 - Date: 10/12/2022

Inspection Photos



Photo 4. There are oil stained soils inside the containment that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06178 - Date: 10/12/2022

Inspection Photos



Photo 5. The burnt up tank remains at the east side of the location and needs to be removed ASAP.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06178 - Date: 10/12/2022

Inspection Photos



Photo 6. Facing toward the pumpjack. The well sign and H2S sign would be more visible from the other side of the pumpjack entering the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06178 - Date: 10/12/2022

Inspection Photos



Photo 7. There was a dripping leak occurring at the pipe fittings.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06178 - Date: 10/12/2022