

Inspection Photos

October 10, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335305

Location Name: GIBSON GULCH UNIT-66S91W/29NWSW

Inspection Document #: 702800819

Garfield County, CO

NWSW Section 29 T6S R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: GIBSON GULCH UNIT-66S91W/29NWSW

Location ID: 335305



Photo 1. Photo taken from the south shows an overview of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800819

Inspection Photos

Location Name: GIBSON GULCH UNIT-66S91W/29NSW

Location ID: 335305



Photo 2. Photo shows production areas at the south of the Location.



Photo 3. Photo shows production areas at the north of the Location. Note, fence is in proper functioning condition.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Number: 702800819

Inspection Photos

Location Name: GIBSON GULCH UNIT-66S91W/29NWSW

Location ID: 335305



Photo 4. Photo shows production areas at the north of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800819

Inspection Photos

Location Name: GIBSON GULCH UNIT-66S91W/29NSW

Location ID: 335305



Photo 5. Photo taken from the north of the Location behind the tanks. No debris was observed on Location, as in previous inspection.



Photo 6. Photo shows a stormwater BMP at the northeast of the Location. The structure is installed with smooth river rock and lacks a geotextile liner. No degradation was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800819

Inspection Photos

Location Name: GIBSON GULCH UNIT-66S91W/29NWSW

Location ID: 335305



Photo 7. Photo taken to the south shows interim areas colonized by perennial grasses. Photo also shows a ditch and berm that will have to be reclaimed/recontoured during final reclamation.



Photo 8. Photo taken to the south shows interim areas colonized by perennial grasses.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800819