

Inspection Photos

API: 011-06072

Operator: STRACHAN EXPLORATION INC

Inspection Date: 10/11/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 011-06072 - Date: 10/11/2022

Inspection Photos



Photo 1. Facing north toward the location. There is an area approximately 150'x100' with no vegetation growth. The surrounding field does not have a crop planted but has vegetation growth. There are likely soil issues that is impact growth of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06072 - Date: 10/11/2022

Inspection Photos



Photo 2. Facing north at the location. There is an area approximately 150'x100' with no vegetation growth. The surrounding field does not have a crop planted but has vegetation growth. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06072 - Date: 10/11/2022

Inspection Photos



Photo 3. Facing south at the location shows no vegetation growth at the former well site. There are likely soil issues that impact growth of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06072 - Date: 10/11/2022

Inspection Photos



Photo 4. Facing west at the location. There is an area approximately 150'x100' with no vegetation growth. The surrounding field does not have a crop planted but has vegetation growth. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06072 - Date: 10/11/2022

Inspection Photos



Photo 5. Facing west at the surrounding undisturbed area which shows vegetation cover compared to the location which has no vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06072 - Date: 10/11/2022