

Inspection Photos

API: 011-06099

Operator: PONCHO PRODUCTION COMPANY

Inspection Date: 10/11/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the former access road. The road has not been reclaimed and consists of undesirable weed such as Kochia and Russian thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06099 - Date: 10/11/2022

Inspection Photos



Photo 2. Facing south toward the location which has not been reclaimed. There are undesirable weeds throughout the location and areas bare vegetation. There is equipment that remains at the south side of the location shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06099 - Date: 10/11/2022

Inspection Photos



Photo 3. Facing southwest. This area appears to be the former tank battery site. There are likely soil issues preventing vegetation growth within this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06099 - Date: 10/11/2022

Inspection Photos



Photo 4. Facing southwest at the south side of the location. There is an abandoned pipe riser that has not been removed shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06099 - Date: 10/11/2022

Inspection Photos



Photo 5. South side of the location facing north. There are areas with no vegetation growth and the abandoned pipe riser remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06099 - Date: 10/11/2022

Inspection Photos



Photo 6. Facing northeast. This area appears to be the former tank battery site. There are likely soil issues preventing vegetation growth within this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06099 - Date: 10/11/2022

Inspection Photos



Photo 7. Facing southeast at the surrounding undisturbed reference area which shows a uniform vegetation cover consisting of Blue grama, Sand dropseed, Prairie threeawn among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 011-06099 - Date: 10/11/2022