

Inspection Photos
Well Name: North Platte K21-O24-34HC
API #05-123-41885



Photo #1 Well

Inspection Photos
Well Name: North Platte K21-O24-34HC
API #05-123-41885



Photo #2 Stained Soil

Photo #3 Mechanical Conditions