

Interim Reclamation and Stormwater Inspection

October 7, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 328006

Inspection Document #: 697504270

Weld County, CO

SWNE Section 33 T4N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. Google Earth aerial imagery from 6/2/2014 illustrates the tank battery during active operations. Photo illustrates the tank battery appears to be in an area considered cropland.



Photo 2. Photo taken from the tank battery location, facing North. Photo illustrates the tank battery consists mostly of bare soil and annual, weedy vegetation.



Photo 3. Photo taken east of the tank battery location, facing North. Photo illustrates the adjacent areas are a mix of brome/alfalfa and the tank battery is within the red-dashed line.