

# Final Reclamation Inspection

October 7, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 329192

Inspection Document #: 697504274

Weld County, CO

SWSE Section 33 T4N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



**Photo 1.** Aerial imagery from 10/13/1984 illustrates pre-disturbance conditions.

Inspection Photos  
Location Name: BRUZEWSKI #33-15F(2)  
Location ID: 329192



**Photo 2.** Google Earth aerial imagery from 5/4/2011 during active operations. Photo illustrates the well location, access road and associated offsite tank battery.





Inspection Photos  
Location Name: BRUZEWSKI #33-15F(2)  
Location ID: 329192



**Photo 3.** Photo taken from the well location, facing South. Photo illustrates bare patches that are not reflective of reference areas.



**Photo 4.** Photo taken from the well location, facing Southwest. See comments under Photo 3.



Inspection Photos  
Location Name: BRUZEWSKI #33-15F(2)  
Location ID: 329192



**Photo 5.** Photo taken from the well location access road, facing West. Photo illustrates the access road has not been reclaimed and was not pre-existing prior to oil and gas operations.



**Photo 6.** Reference photo taken southeast of the well location, facing South.