

# Final Reclamation Inspection

October 7, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 336579

Inspection Document #: 697504278

Weld County, CO

SWNW Section 33 T4N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos

Location Name: UPRC-64N66W 33SWNW

Location ID: 336579



**Photo 1.** Aerial imagery from 10/13/1984 illustrates pre-disturbance conditions. Red-circle is the approximate location of the tank battery that was built. There appears to be a pre-existing access road along the eastern portion of the crop fields.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697504278

Inspection Photos  
Location Name: UPRC-64N66W 33SWNW  
Location ID: 336579



**Photo 2.** Photo taken from the associated tank battery location, facing West. Photo illustrates all equipment has been removed but the tank battery has not been reclaimed.



**Photo 3.** Photo taken from the associated tank battery location, facing Northeast. See comments under Photo 2.



Inspection Photos  
Location Name: UPRC-64N66W 33SWNW  
Location ID: 336579



**Photo 4.** Photo taken from the well location, facing East. Photo illustrates desirable vegetation is evident but will remain in-process since it is not reflective of reference areas.



**Photo 5.** Photo taken from the well location, facing South. See comments under Photo 4.



Inspection Photos  
Location Name: UPRC-64N66W 33SWNW  
Location ID: 336579



**Photo 6.** Photo taken from the well location, facing West. See comments under Photo 4.



**Photo 7.** Photo taken from the well location, facing North. See comments under Photo 4.

