

# Inspection Photos

September 10, 2022

Operator: Timberline Energy Inc - #88348

Location ID: 322327

Location Name: LILLIAN B. SMITH, ET AL-67S91W /22SENW

Inspection Document #: 702800787

Garfield County, CO

SENW Section 22 T7S R91W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: LILLIAN B. SMITH, ET AL-67S91W /22SENW

Location ID: 322327



**Photo 1.** Photo taken from the northeast shows an overview of the Location. Arrows indicate the well marker (left) and riser (right).



**Photo 2.** Photo taken from the west shows an overview of the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800787



## Inspection Photos

Location Name: LILLIAN B. SMITH, ET AL-67S91W /22SENW

Location ID: 322327



**Photo 3.** Photo taken from the center of the Location shows the well marker, note valve present.



**Photo 4.** Photo taken from the northwest shows a riser remaining on Location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800787



## Inspection Photos

Location Name: LILLIAN B. SMITH, ET AL-67S91W /22SENW

Location ID: 322327



**Photo 5.** Photo shows an example of areas of poor vegetation establishment and bare ground.



**Photo 6.** Photo shows an example of areas of poor vegetation establishment and bare ground.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800787



## Inspection Photos

Location Name: LILLIAN B. SMITH, ET AL-67S91W /22SEW

Location ID: 322327



**Photo 7.** Photo shows an example of areas of poor vegetation establishment and bare ground.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800787