

Inspection Photos

October 11, 2022

Operator: True Oil LLC - #90450

Location ID: 313095

Location Name: CADDIS FEDERAL-611N91W/9NWSE

Inspection Document #: 702800825

Moffat County, CO

NWSE Section 9 T11N R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CADDIS FEDERAL-611N91W/9NWSE
Location ID: 313095



Photo 1. Photo taken from the Location entrance shows the access road is bare and compacted in tracks. Vehicles are utilizing the road, potentially compromising revegetation.



Photo 2. Photo taken to the south shows the start of the access road. Portions of the road are revegetated, however, perennial cover is not uniform. Bare ground and annual weeds are common and vehicles are utilizing the road causing compaction and potentially compromising revegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800825

Inspection Photos
Location Name: CADDIS FEDERAL-611N91W/9NWSE
Location ID: 313095



Photo 3. Photo taken from the location entrance shows an overview of the reclaimed location.



Inspection Photos

Location Name: CADDIS FEDERAL-611N91W/9NWSE

Location ID: 313095



Photo 4. Photo taken from the center of the Location shows the start of disturbed area vegetation monitoring transect #1.



Photo 5. Photo taken from the center of the Location shows the ground surface at the start of disturbed area vegetation monitoring transect #1.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800825

Inspection Photos

Location Name: CADDIS FEDERAL-611N91W/9NWSE

Location ID: 313095



Photo 6. Photo taken from the center of the Location shows the end of disturbed area vegetation monitoring transect #1.



Photo 7. Photo taken from the center of the Location shows the ground surface at the end of disturbed area vegetation monitoring transect #1.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800825

Inspection Photos
Location Name: CADDIS FEDERAL-611N91W/9NWSE
Location ID: 313095



Photo 8. Photo taken from the adjacent reference area to the north of the Location shows the start of reference area vegetation monitoring transect #1.



Photo 9. Photo taken from the adjacent reference area to the north of the Location shows the ground surface at the start of reference area vegetation monitoring transect #1.

Inspection Photos

Location Name: CADDIS FEDERAL-611N91W/9NWSE

Location ID: 313095



Photo 10. Photo taken from the adjacent reference area to the north of the Location shows the end of reference area vegetation monitoring transect #1.



Photo 11. Photo taken from the adjacent reference area to the north of the Location shows the ground surface at the end of reference area vegetation monitoring transect #1.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800825

Inspection Photos

Location Name: CADDIS FEDERAL-611N91W/9NWSE

Location ID: 313095



Photo 12. Photo taken from the east shows portions of the Location where perennial establishment is relatively low. Areas of poor establishment appear to be at former equipment footprints and working pad area road. Note also vehicle tracks.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800825