

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403201736

Date Received:
10/19/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10575

Name of Operator: 8 NORTH LLC

Address: 370 17TH STREET SUITE 5200

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Mike Storey

970-939-6353

mstorey@civiresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696304495

Inspection Date: 10/05/2022

FIR Submit Date: 10/05/2022

FIR Status: _____

Inspected Operator Information:

Company Name: 8 NORTH LLC

Company Number: 10575

Address: 370 17TH STREET SUITE 5200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 461138

Location Name: WILSON Number: 1160-29-22 JS County: _____

Qtrqtr: NWN Sec: 29 Twp: 11N Range: 60W Meridian: 6
W

Latitude: 40.896903 Longitude: -104.124462

FACILITY - API Number: 05-123-00 Facility ID: 461138

Facility Name: WILSON Number: 1160-29-22 JS

Qtrqtr: NWN Sec: 29 Twp: 11N Range: 60W Meridian: 6
W

Latitude: 40.896903 Longitude: -104.124462

CORRECTIVE ACTIONS:

1 CA# 165071

Corrective Action: Comply with Rule 606

Date: 10/14/2022

Response: CA COMPLETED

Date of Completion: 10/11/2022

Operator
Comment:

Risers have been marked in compliance with Rule 606.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr Regulatory Analyst

Date: 10/19/2022 8:47:22 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403201741	Inspection Photos
-----------	-------------------

Total Attach: 1 Files