

# Final Reclamation and Stormwater Inspection

Date: 10/11/2022

Operator: MALLARD EXPLORATION LLC - 447825

Location ID: 447825

Inspection Document #: 696105511

Weld County, CO

NESW Section 31 T9N R59W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Shull Pad  
Location ID: 447825



**Photo 1.** Taken from approximate abandoned wells location, facing north. Photo illustrates location was never built, with no visible evidence of oil and gas equipment or disturbances.

Inspection Photos  
Location Name: Shull Pad  
Location ID: 447825



**Photo 2.** Facing east, see comments in Photo 1.

Inspection Photos  
Location Name: Shull Pad  
Location ID: 447825



**Photo 3.** Facing south, see comments in Photo 1.

Inspection Photos  
Location Name: Shull Pad  
Location ID: 447825



**Photo 4.** Facing west, see comments in Photo 1.