

Inspection Photos
Location Name: WPF III-66N64W/18NWNE
Location #: 323559



Colorado Oil & Gas Conservation Commission
Weld County
+40.491544 -104.590847
94° E
2022-10-18 13:22

Photo #1

WPF III A18-2 (05-123-13195) Wellsite
Temporarily Abandoned | TA
Weeds need cleared



Colorado Oil & Gas Conservation Commission
Weld County
+40.493060 -104.592915
115° SE
2022-10-18 13:54

Photo #2

WPF III A18-2 Battery site
Inactive / Shut-down
Formerly served:
WPF III A 18-7, Carlson A18-17;
Plugged & Abandoned | PA

Inspection Photos
Location Name: WPF III-66N64W/18NWNE
Location #: 323559




Photo #3
WPF III A18-2 Battery site
Inactive / Shut-down
Crude oil tank; SE corner



Photo #4
WPF III A18-2 Battery site
Inactive / Shut-down
ECDs, Separator

Inspection Photos
Location Name: WPF III-66N64W/18NWNE
Location #: 323559



Colorado Oil & Gas Conservation Commission
Weld County
+40.492993,-104.592666
180° S
2022-10-18 13:56

Photo #5
WPF III A18-2 Battery site
Inactive / Shut-down
Battery sign 1



Colorado Oil & Gas Conservation Commission
Weld County
+40.492997,-104.592796
175° S
2022-10-18 13:56

Photo #6
WPF III A18-2 Battery site
Inactive / Shut-down
Battery sign 2