

Interim Reclamation and Stormwater Inspection

Date: 10/11/2022

Operator: NOBLE ENERGY LLC - 100322

Location ID: 445191

Inspection Document #: 696105537

Weld County, CO

NENE Section 15 T9N R59W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LC15-01 Pad
Location ID: 445191



Photo 1. Taken near the entrance to the location, facing west. Photo illustrates annual weedy vegetation (kochia) within the interim reclamation areas. Some desirable vegetation was also observed during this inspection; e.g. blue grama, buffalo grass, and other native species.

Inspection Photos
Location Name: LC15-01 Pad
Location ID: 445191



Photo 2. Taken near the location's entrance, facing south. See comments in photo 1.

Inspection Photos
Location Name: LC15-01 Pad
Location ID: 445191



Photo 3. Taken from eastern portion of location, facing west. See comments in photo 1.

Inspection Photos
Location Name: LC15-01 Pad
Location ID: 445191



Photo 4. Taken from southern portion of location, facing west. See comments in photo 1.