

Inspection Photos

API: 071-06762

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/20/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06762 | Date: 10/20/2022

Inspection Photos



Photo 1. Facing northeast along the main access road past the compressor. There is erosion along the roadside in this area and the culvert is partially filled in with sediment. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06762 | Date: 10/20/2022

Inspection Photos



Photo 2. Facing west along the main access road. There is erosion along the roadside in this area. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06762 | Date: 10/20/2022

Inspection Photos



Photo 3. There is erosion and vehicle rutting along the access road near the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06762 | Date: 10/20/2022

Inspection Photos



Photo 4. Facing west toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06762 | Date: 10/20/2022

Inspection Photos



Photo 4. There is oily fluid in the engine skid that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06762 | Date: 10/20/2022