

Inspection Photos

API: 071-08000

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/20/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08000 | Date: 10/20/2022

Inspection Photos



Photo 1. Facing south toward the location..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08000 | Date: 10/20/2022

Inspection Photos



Photo 2. Facing toward the wellhead and production pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08000 | Date: 10/20/2022

Inspection Photos



Photo 3. Facing back north at the interim reclamation area. The location is stabilized with perennial vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08000 | Date: 10/20/2022