

Inspection Photos

Loc: 309334

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/20/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc# 309334 | Date: 10/20/2022

Inspection Photos



Photo 1. Facing south along the access road. This area of the road has been repaired and stabilized with gravel. Approximate Lat/Long:37.23652,-104.69804



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc# 309334 | Date: 10/20/2022

Inspection Photos



Photo 2. Facing south along the access road. This area of the road has been repaired and stabilized with gravel. Approximate Lat/Long:37.24515,-104.68856



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc# 309334 | Date: 10/20/2022

Inspection Photos



Photo 3. The road has been stabilized with gravel. Approximate Lat/Long:37.246320,-104.679854



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc# 309334 | Date: 10/20/2022

Inspection Photos



Photo 4. Facing east toward the access road and location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc# 309334 | Date: 10/20/2022

Inspection Photos



Photo 5. Facing northeast toward the wellsite.

