

Inspection Photos

API: 071-06838

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 10/20/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06838 | Date: 10/20/2022

Inspection Photos



Photo 1. Facing east at the beginning of the access road. The road has been regraded and repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06838 | Date: 10/20/2022

Inspection Photos



Photo 2. Facing northeast along the access road. The road has been regraded and repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06838 | Date: 10/20/2022

Inspection Photos



Photo 3. Facing southeast along the access road. The remainder of the road is stabilized and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06838 | Date: 10/20/2022

Inspection Photos



Photo 4. Facing south along the access road entering into the canyon.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06838 | Date: 10/20/2022

Inspection Photos



Photo 5. Facing southwest along the road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06838 | Date: 10/20/2022

Inspection Photos



Photo 6. Facing southwest along the road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06838 | Date: 10/20/2022

Inspection Photos



Photo 7. Facing toward the cut slope which is stabilized with perennial vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06838 | Date: 10/20/2022

Inspection Photos



Photo 8. Facing toward the location which is stabilized with perennial vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06838 | Date: 10/20/2022