

Inspection Photos

October 20, 2022

Operator: Crowheart Energy LLC - #10776

Location ID: 313162

Location Name: Kaline SWD-612N94W /23NENW

Inspection Document #: 702800838

Moffat County, CO

NENW Section 23 T12N R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Kaline SWD-612N94W /23NENW
Location ID: 313162



Photo 1. Photo taken from the south, at the Location entrance shows an overview of the Location.



Photo 2. Photo taken from the east shows an overview of the Location including recently ripped interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800838

Inspection Photos
Location Name: Kaline SWD-612N94W /23NENW
Location ID: 313162



Photo 3. Photo shows the tank battery sign. Sign does not comply with Rule 605; Telephone number for local emergency services (911 where available) and the public road used to access the tank battery site are not posted.



Photo 4. Photo shows trash/debris.



Inspection Photos
Location Name: Kaline SWD-612N94W /23NENW
Location ID: 313162




Photo 5. Photo shows the maximum depth of shovel penetration on the ripped interim area is 30 cm (12 inches). Some areas appeared to be ripped shallower.

Inspection Photos

Location Name: Kaline SWD-612N94W /23NENW

Location ID: 313162



Photo 6. Photo shows a the Location has been ripped in one direction. Shovel was unable to penetrate a continuous strip of unripped soil. “Cross-ripping” means passes should be overlapping. Red line indicates direction of rip. Blue line indicates additional rip direction needed.



Photo 7. Photo shows shovel unable to penetrate a continuous unripped strip of soil.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800838