

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403194224

Date Received:

10/11/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

Labowskie, Steve

steve.labowskie@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500471

Inspection Date: 09/23/2022

FIR Submit Date: 09/23/2022

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 307028

Location Name: PHILLIPS GU A Number: 3R County: LA PLATA

Qtrqtr: NWSE Sec: 33 Twp: 34N Range: 9W Meridian: M

Latitude: 37.145530 Longitude: -107.826648

FACILITY - API Number: 05-067- -00 Facility ID: 441563

Facility Name: PHILLIPS A Number: 3R2

Qtrqtr: NWSE Sec: 33 Twp: 34N Range: 9W Meridian: M

Latitude: 37.145530 Longitude: -107.826648

CORRECTIVE ACTIONS:

1 ☒ CA# 164764

Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 10/08/2022

Response: CA COMPLETED

Date of Completion: 10/04/2022

Operator Comment: Stain removed from around wellhead.

COGCC Decision: Approved pending re-inspection

CA from previous inspection Doc# 702500471 has been satisfactorily completed, pending reinspection.

Date: 10/08/2022

Date of Completion: 10/04/2022

Operator Comment:	Weeds removed from inside pit berm.
-------------------	-------------------------------------

Approved pending re-inspection
CA from previous inspection Doc# 702500471 has been satisfactorily completed, pending reinspection.

Date: 10/08/2022

Date of Completion: 10/04/2022

Operator Comment:	Equipment removed from location.
----------------------	----------------------------------

Approved pending re-inspection

CA from previous inspection Doc# 702500471 has been satisfactorily completed, pending reinspection.

Comment:	CA complete. See attached photos.
----------	-----------------------------------

Print Name: Grace Bryson

Title: Permitting Specialist I Date: 10/11/2022 3:35:56 PM

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Total Attach: 2 Files