

Inspection Photos
Location Name: RUBIX-66N64W/32NWNW
Location #: 330218



Photo #1
Rubix A 32-04 (05-123-18644) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 50 yds.



Photo #2
QC USX A32-19, Rubix A 32-03, A 32-04,
Johnson A 32-06
Battery site
Abandoned: ALL Equipment Removed