

Inspection Photos

Location Name: JOHNSON A-66N64W/32SENW

Location #: 330219



Photo #1

Johnson A 32-06 (05-123-18645) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 20 yds.



Photo #2

QC USX A32-19, Rubix A 32-03, A 32-04,

Johnson A 32-06

Battery site

Abandoned: ALL Equipment Removed