

# Final Reclamation Inspection

June 22nd, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 322652

Inspection Document #: 701900687

SESE Section 27 T6N R65W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Swanson 44-22  
Location ID: 322652



**Photo 1.** 2021 aerial imagery of the well pad and tank battery. Note: well pad and tank battery shared a disturbance.



Inspection Photos  
Location Name: Swanson 44-22  
Location ID: 322652



**Photo 2.** Overview photos of the tank battery/well pad disturbance taken at ground level from the western (left) and northern (right) edges. Note: disturbance falls within a horse corral, however, disturbance does not appear consistent with area just to the east (also within horse corral) and has a higher density of weeds (field bindweed).



Inspection Photos  
Location Name: Swanson 44-22  
Location ID: 322652



**Photo 3.** Tank battery/well pad reference area.